McNaely Oil Burner Service 603 County Rd. 2 Lanadowne, Ontario KOE 11.0 513-382-0221

Fuel Oil Distribution Inspection

Above Ground Tanks - Inside

| Owner/Operator: GBRADLEY Ocation: 1329 EDEN GROVE Glephone #: LANSDOWNE O | TOT ROE TES | |
|--|-------------------|----------------------|
| Owner Address: | Tank # 1 | Tank#2 |
| 7-73 W | Zon Gas | |
| ype of Tank. le:ULC-5602 Don BLE FOTTOM | ZOO GAZ GRANBY | |
| Nanufacturer | | |
| Date of Manufacture NOU 2023 INSTALL | ED FEB 2024 | |
| Serial # | F/16600037 | Oves Ono |
| and approved for present use? | Oyes Ono | 0,45 |
| n-die accordante with they by code: | Oyes Ono | Ore |
| Is tank installed in account Are the tank vent and fill pipes properly installed and | Oyes Ono | Oyes One |
| | Oves Ono | Oyes Ono |
| - winned with proper the Lap. | | Oyes Ono |
| s to tank equipped with a proper gauge and whome: | O/es Ono | Cyes Ono |
| is amounted on firm base? | Oyes Ono | Oyes Ono |
| is tank support in good condition, non-combustible | Oyes Ono | O - Ona |
| | Oyes Ono Ona | Oyes One Cam |
| and stable? 8. If two tank are joined, are they installed on a | 0. 0 | Oves Ono Ona |
| 9. If two tanks are bottom connected, are they | Oves Ono Ona | O/- |
| connected with 2" pipe? | Cyes Ono | Oyes Ono |
| tree of leaks of any significant | Gyes Ono | Oyes Ono |
| 11. Is the tank and piping painted to prevent corrosion? | Oves Ono | Oyes Ono |
| 12. Are burner supply/return lines free of compression | 1. | Owes Ono |
| tittings? | Oyes Ono | O,es o |
| 13. Are hurner supply/territorial and chasel? and protected or underground and chasel? | Oyes Ono | Oyes Ona |
| Aco burger Supply/return lines in Acoustic | 10, | Oyes Ono |
| | 017 | Oyes Ono |
| 16. Is an approved fixer installed with a temperature | Cyes Ono | 2 |
| 16. Is an approved 538°C(1000°F)? 17. Is the fill/vent pipe steel or galvanized construction? | Oyes Ono | Oves |
| | Gyes Ono | Oyes Ono |
| 18. Is the tank located at least 2 min to experience by fire rated the tank protected from the appliance by fire rated | | 1.7 |
| (166 ESUR humanu) | _ | |
| Rotes(any NO answers must be explained in this section and | | 1-1 |
| itotesfam; NO answers must be altected or tagged) affected equipment repaired, replaced or tagged) Committees: | Date: FEB 6/ | 2 9 ense# 0737154 |