TRI COUNTY INSPECTION

Residential - Commercial - Industrial

contact@tricount	yinspect.com
------------------	--------------

613-847-3810

SEPTIC INSPECTION REPORT

Property and Contact Information

Client Name: 6 Goodon Grand Louisizer, Security. 3408 Property Address: 6 3604 Conny Lund 1, Perc.		
3 40 8 Property Address: <u> 3 40 8</u>	n Zund / PEC.	
Toporty Address to		
Septic Information		
Date of Inspection: M. Nov 29/2024	Weather conditions:occesso	
Age of Home:	Age of System: 70+	
How many bedrooms:6	# Occupants: 4+	
Type of system: (Septic Tank). Sep	otic tank w/Pump Cesspool	
Type of Drainage Area: Leaching Field	Sand Mound Other:	
Type of Dramage Area.	Cana i Touria (L.)	
System Function		
Needs to be Pumped Acc	ceptable (no repairs needed) • Needs Repairs	
Complete System Replacement Further Investigation Needed		
Explain:		
Septic Tank: Acceptable Una	acceptable Explain:	
How many Septic Tanks: /		
How many Drain Fields or Drainage Areas:		
Effluent Level Acceptable 💯 Bel	ow Outlet High	
Sludge Level Acceptable <u>Ses</u> High		
Sludge depth in Inches		
Inlet Baffle Not Visiko Outlet baffle Not Visiko Tank Baffle Wall Now You		

Lids Concluse Risers Nont Drain Field 6001).
Was the field Probed? Wes If NO Explain:
Was it Saturated?
Is the System/Drain field adequate for the Home?
Does the Tank Require Pumping?
Did the effluent level rise during the stress test?
Did any effluent come back into tank Indicating a problem?
Approximately how much water was flushed through the system to test the drainage area?
150-170 Baccons
Was part of the inspection the interior of the home? <u>YES</u> Cleanout in basement? <u>YES</u>
System Location
Is the system installed at the required distances away from the Well?
Approximate distance from home?
Approximate distance from Septic to Well
RECCOMENDATIONS
TANK SIZE / SYSTEM WELL BELOW TODAYS STANDARDS,
TANK SIZE SYSTEM WELL BELOW TODAYS STANDARDS, SYSTEM IS WELL PAST ITS LIFE EXPECTANCES, NOT ALL PLEMBIN DRAINS TO SEPTIL FROM HOUSE, AS THEY DRAIN ON THE GROUND
DISCLAMER
The inspection has many Limitations due to the fact the system is mostly buried underground. This report can only guarantee the system's function stated in the report on the day of the inspection.
INSPECTOR: Jason Steele SIGNED:
BCIN#122266 DATE: DEC 2/2024

TRI COUNTY INSPECTION