TRI COUNTY INSPECTION

Residential - Commercial - Industrial

con	tac	t@tri	icou	ntvir	ารท	ect.	com
CUII	lac	twitt	oou		ıσμ	oot.	COLL

613-847-3810

SEPTIC INSPECTION REPORT

Property and Contact Information

Client Name: 602) Co2) N ESTATE SAMCES.							
Property Address: 1540 Gannon Than , CLO7NV.							
Septic Information							
Date of Inspection: ০০০ 14/2024 Weather conditions:							
Age of Home: W Age of System:							
How many bedrooms: # Occupants:							
Prostric							
Type of system: Septic Tank Septic tank w/Pump Cesspool							
Type of Drainage Area: Leaching Field Sand Mound (59) Other:							
System Function							
Needs to be Pumped Acceptable (no repairs needed) Meeds Repairs							
Complete System Replacement Further Investigation Needed							
Explain:							
Septic Tank: Acceptable Unacceptable Explain:							
How many Septic Tanks:							
How many Drain Fields or Drainage Areas: /							
Effluent Level Acceptable 125. Below Outlet High							
Sludge Level Acceptable High							
Sludge depth in Inches							
nlet Baffle Assic Cool Outlet baffle Assic Cool Tank Baffle Wall Cool.							

Lids 6000 Risers Recommond. Drain Field 6000 .					
Was the field Probed? If NO Explain:					
Was it Saturated?					
Is the System/Drain field adequate for the Home?					
Does the Tank Require Pumping?					
Did the effluent level rise during the stress test?					
Did any effluent come back into tank Indicating a problem?					
Approximately how much water was flushed through the system to test the drainage area?					
150 agricons.					
Was part of the inspection the interior of the home? Yes Cleanout in basement? Yes.					
System Location					
Is the system installed at the required distances away from the Well?					
Approximate distance from home? 5' LANG IN WA 71.1 Seffing.					
Approximate distance from Septic to Well					
RECCOMENDATIONS					
MINTANES. IF REQUISED (10 DILLING)					
maintanco. IE Regulos (no Melino).					
DISCLAMER					
The inspection has many Limitations due to the fact the system is mostly buried underground. This report can only guarantee the system's function stated in the report on the day of the inspection.					

INSPECTOR: Jason Steele

BCIN#122266

TRI COUNTY INSPECTION