## TRI COUNTY INSPECTION

## Residential - Commercial - Industrial

contact@tricountyinspect.	.con	ĭ
---------------------------	------	---

Sludge Level Acceptable <u>Fes.</u> High\_\_\_\_\_

Inlet Baffle Congress Outlet baffle Congress Tank Baffle Wall Congress.

613-847-3810

SEPTIC INSPECTION REPORT
Property and Contact Information
Client Name: 600 Cookdon Downsizing desirate Senices
Property Address: 199 293 How Cub Road wasa.
Septic Information
Date of Inspection: Weather conditions: over 14.
Age of Home: 🕮
How many bedrooms:# Occupants:
Type of system: Septic Tank Septic tank w/Pump Cesspool
Type of Drainage Area: Leaching Field Sand Mound (99) Other:
System Function
Needs to be Pumped Acceptable (no repairs needed) Meeds Repairs
Complete System Replacement Further Investigation Needed
Explain:
Septic Tank: Acceptable Unacceptable Explain:
How many Septic Tanks: /
How many Drain Fields or Drainage Areas: /
Effluent Level Acceptable <u>FB</u> Below Outlet High

Le Commended  Lids <u>(mon</u> Risers <del>Parison</del> Drain Field (con)
Was the field Probed? We State If NO Explain:
Was it Saturated?
Is the System/Drain field adequate for the Home?
Does the Tank Require Pumping?
Did the effluent level rise during the stress test?
Did any effluent come back into tank Indicating a problem?
Approximately how much water was flushed through the system to test the drainage area?
150 boscons.
Was part of the inspection the interior of the home? <u>Yes</u> Cleanout in basement? <u>Yes</u> .
System Location
Is the system installed at the required distances away from the Well?
Approximate distance from home?5'
Approximate distance from Septic to Well 50 %
RECCOMENDATIONS
DISCLAMER
The inspection has many Limitations due to the fact the system is mostly buried underground. This report can only guarantee the system's function stated in the report on the day of the inspection.
INCOPPORTOR ASSOCIATION OF THE PROPERTY OF THE
INSPECTOR: Jason Steele SIGNED: SIGNED: DATE: Nov. 16/2024

TRI COUNTY INSPECTION