

WETT RECOMMENDED INSPECTION CHECKLIST



Requested by: Nicky Breeze	Inspection location: Same as requested or: Gordon's Downsizing & Estate services	
Address:	Address: 1605 Grant Avenue Cornwall, Ontario K6J 5K4	
Email:	Email: nicky@gogordons.com	
Phone No.:	Phone No.: 613-542-0963	
Joel Bouchard Inspector's name:	6926 WETT No.:	
Reason(s) for inspection: Insurance & Home	sale	
Level of inspection requested:		
Date of request:	Date of inspection: Sept 5, 2024	

Note: inspection results shown are what was present/noted at time of inspection.

This report documents findings at the time of the inspection. Compliance is referenced to currently published applicable codes and standards.

Wood Energy Technology Transfer Inc.	TT RECOM	Masonry	INSPECTION CHECKLIST Y FIREPLACE
Constructed with the building:	ONo (Yes OUn	known Approximate age: 1979
Chimney is:	Exterior	Total system	height: 24'
Fireplace is: Interior	Exterior		
Fireplace location: Baseme	ent 🔘	Main Floor	Other: Living room
Fireplace opening measuremen	nts: Heig	_{ht:} 25"	Width: 34"
			eat form Other:
			Ounknown
OLC 3039 Listing agency: _			Onknown
Type of chimney: Masonry	Ootl	ner:	
Fireplace built by: Builder		Date:	1979 Unknown
			nsidered for comment. le some components marked UTI.
GENERAL	REQUIRED	Actual(s)	CODE COMPLIANCE
1. Footings		concrete	N/A Yes No UTI
Support for fire chamber and the hearth		concrete	N/A Yes No UTI
3. Hearth extension / side	8	20	N/A Yes No UTI
4. Hearth extension / front	18	12	N/A Yes No UTI
5. Fireplace masonry wall thickness		+/-3.5"	N/A Yes No UTI
6. Fire chamber depth	12	21"	N/A Yes No UTI
7. Support above opening		Steel-brick	N/A Yes No UTI
8. Non-combustible facing /			O N/A O Vec ONO O LITT

N/A Yes No UTI

9. Non-combustible facing /

Masonry Fireplace - page 2 10. Combustible mantle Depth: N/A Yes O No O UTI clearance / side 11. Combustible mantle Depth: (N/A Yes No clearance / top 12. Heat duct openings) Yes O No clearance N/A Yes) No UTI 13. Damper 14. Clearance to metal exposed N/A) Yes (UTI (No to the interior N/A Yes No (UTI 15. Clearance to framing 16. Smoke chamber slope from N/A Yes OUTI No the vertical >< 45° 17. Smoke chamber wall +/-3.5" N/A) Yes No thickness 18. Smoke chamber clearance () N/A Yes No OUTI to framing 19. 20. **OTHER CONSIDERATIONS** COMMENTS 21. Combustion air required? ☐ Yes ☐ No 22. Glass doors Yes 23. Fireplace screen Yes Yes - Upgrade as needed 24. Carbon monoxide alarm 25. Smoke alarm Yes - Upgrade as needed Additional information: The fireplace appears in satisfactory condition but chimney dirty and due for cleaning This type of fireplace is designed mostly for ambiance fire and won't generate much heat for the house. Do not rely on the fireplace to provide heat supply to the house itself. Note: UTI - Unable to inspect items are located inside the walls or behind the fireplace brick which are not visible. File Reference #: 1605 Grant Date: Sept 5, 2024

File reference No.: 1605 Grant				
Photos taken: Yes No				
This checklist contains 4 pages in total. This report contains 5 pages in total.				
Comments and Observations:	.1 10			
All non-compliance ratings should be	considered for comment.			
An annual chimney sweep and inspection technician as needed for safety.	n before using should be completed by a certified			
Review guide from CMHC on residential	wood heating on safety measures for users and occupants			
	foration, wear and tear. Monitor and the top area should be on protected with a sealed metal chimney cap to reduce risk stegrity.			
	ont of the fireplace extends only 12" and should extend a ograded as needed before using for safety.			
Please attach ac	dditional page(s) for this section.			
	Inspector Signature:			
Customer Signature: Nicky Breeze	Digital Signature:			
Date: Sept 5, 2024	Date: Sept 5, 2024			

WETT Recommended Inspection Checklist









