

Certificate of Analysis

Grayspec Home Inspection Services

125 Elm St
Gananoque, ON K7G2T1
Attn: Jason Graydon

Client PO:
Project: 735 County Rd. 2, Landsdowne
Custody:

Report Date: 13-Aug-2024
Order Date: 7-Aug-2024

Order #: 2432208

This Certificate of Analysis contains analytical data applicable to the following samples as submitted :

Parcel ID	Client ID
2432208-01	Roof
2432208-02	Floor space second floor
2432208-03.1	Bathroom flooring
2432208-03.2	Bathroom flooring

Approved By:



Emma Diaz
Senior Analyst

Certificate of Analysis
 Client: Grayspec Home Inspection Services
 Client PO:

Report Date: 13-Aug-2024
 Order Date: 7-Aug-2024
 Project Description: 735 County Rd. 2, Landsdowne

Asbestos, PLM Visual Estimation **MDL - 0.5%**

Parcel ID	Sample Date	Colour	Description	Asbestos Detected	Material Identification	% Content
2432208-01	07-Aug-24	Grey	Vermiculite	Yes	Client ID: Roof	[AS-VER2]
					Actinolite	1
					Non-Fibers	99
2432208-02	07-Aug-24	Brown	Vermiculite	Yes	Client ID: Floor space second floor	[AS-VER2]
					Actinolite	1
					Non-Fibers	99
2432208-03.1	07-Aug-24	Brown	Tile	Yes	Client ID: Bathroom flooring	
					Chrysotile	1
					Non-Fibers	99
2432208-03.2	07-Aug-24	Yellow	Mastic	No	Client ID: Bathroom flooring	
					Non-Fibers	100

** Analytes in bold indicate asbestos mineral content.

Analysis Summary Table

Analysis	Method Reference/Description	Lab Location	Lab Accreditation	Analysis Date
Asbestos, PLM Visual Estimation	AppE to SubE of 40CFR Part763 and EPA/600/R-93/116	1 - Mississauga	CALA 3762	12-Aug-24

Mississauga Lab: 15 - 6800 Kitimat Rd Mississauga, Ontario, L5N 5M1

Qualifier Notes

Sample Qualifiers :

AS-VER2: Insufficient sample for Chatfield Method. Note that TEM analysis is recommended for confirmation of asbestos in vermiculite.

Work Order Revisions | Comments

None



TRUSTED.
RESPONSIBLE
RELIABLE

Parcel ID: 2432208



Chain of Custody
(Lab Use Only)

Page ___ of ___

Client Name: Grayspec Home Inspection Services	Project Reference: 735 County Rd. 2, Landsdowne	Turnaround Time: <input type="checkbox"/> Immediate <input type="checkbox"/> 1 Day <input type="checkbox"/> 4 Hour <input type="checkbox"/> 2 Day <input type="checkbox"/> 8 Hour <input type="checkbox"/> 3 Day <input checked="" type="checkbox"/> Regular
Contact Name: Jason Graydon	Quote #:	
Address: Gananoque ON	PO #:	
	Email Address: jason.graydon@grayspec.ca	
Telephone: 613 227-9272	Date Required: _____	

ASBESTOS & MOLD ANALYSIS

Matrix: Air Bulk Tape Lift Swab Other Regulatory Guideline: ON QC AB SK Other:

Analyses: Microscopic Mold Culturable Mold Bacteria GRAM PCM Asbestos PLM Asbestos Chatfield Asbestos TEM Asbestos

Parcel Order Number: 2432208		Asbestos - Bulk			
Sample ID	Sampling Date	Air Volume (L)	Analysis Required	Identify Distinct Building Materials to Be Analyzed (if not specified, all materials identified will be analyzed) *	Positive Stop?
1	Roof	Aug 7, 24	Chatfield	Vermiculite	<input type="checkbox"/>
2	Floor space second floor	Aug 7, 24	Chatfield	Vermiculite	<input type="checkbox"/>
3	Bathroom flooring	Aug 7, 24	PLM	Tile	<input type="checkbox"/>
4					<input type="checkbox"/>
5					<input type="checkbox"/>
6					<input type="checkbox"/>
7					<input type="checkbox"/>
8					<input type="checkbox"/>
9					<input type="checkbox"/>
10					<input type="checkbox"/>
11					<input type="checkbox"/>
12					<input type="checkbox"/>

* If left blank, all distinct materials identified in the samples will be analyzed and reported separately as per EPA 600/R-93/116. Additional charges will apply.

Comments:			Method of Delivery: Walk in
Relinquished By (Sign):	Received at Depot: <i>[Signature]</i>	Received at Lab: <i>[Signature]</i>	Verified By: <i>[Signature]</i>
Relinquished By (Print):	Date/Time: Aug 7 13:45	Date/Time: <i>[Signature]</i> 16-6-24	Date/Time: <i>[Signature]</i> 16-6-24