

308 Brock Street Gananoque, Ontario Canada, K7G 1K6

(613) 532-0081 email askwill@teksavvy.com www.askwill.ca

Client Information Name:	Well Location: Address: 227 SACMON RIVER Rd.
Address:	
	Well Tag:
Phone: (H) (W)	GPS Coordinance: N . W
Inspection: Good Fair Poor N/A  Pump	Good Fair Poor N/A  Water Analysis:  Well
3 3/ 29 4 6 32/ 28 5 33′ 28′ 4 V6 6 3 4′ 28 7 8 35′ 9 35′ 10 15 20 35′ 25 1 30 35′ 27′ 26′ 27′	Notes and Recommendations  PATER FILTRATION NEEDS REPLACING  DISIDER WIRD VIOLET LIGHT  ERMIN PROOF WELL CAP.
Static 27 ft. Static at end of pumping 35' ft. Final recovery 27' ft. Total pumped 504 usgal.	
The data in the attached table supports the conclusion that the well is producing 8 · Uusgal per minute.	

I hereby cetifiy that the data on this report is true and accurate to my knowledge at the time of testing.

Name: W/LL HAMILTON Signature: WWW. Date: NOU.08, 2027

The pumping test has been done in accordance with the requirements in the Water Act and the Ground Water Protection Regulation.

PLEASE NOTE: The data recorded in this pumping test report reflect conditions at the time of the test. Water levels, well performance, estimated long-term well yield and water quality are not guaranteed as they are influenced by a number of factors, including natural variability, human activities, and condition of the works, which may change over time.